

METHODS AND APPARATUS FOR PULSED DOPING OR DRYING A SOOT PREFORM

Abstract

5 A method of manufacturing an optical waveguide preform includes providing a
first process gas atmosphere to a soot preform contained in a vessel. The first
atmosphere is held in the vessel for a first reacting time sufficient to at least partially
dope or dry the soot preform. The vessel is then at least partially refilled with a second
doping or drying atmosphere. The second doping or drying atmosphere is held in the
10 vessel for a second reacting time sufficient to further dope or dry the soot preform.

卷之三